



DIAGNOSIS AND PROBLEM IDENTIFICATION

VTrans Needs Evaluation and Preliminary Alternatives











Offset Intersections

- The signalized Tate Springs Road intersections are closelyspaced and likely less efficient.



Lack of Bicycle Facilities

- Bicycle lanes are not present along the corridor.



Pedestrian Accommodations

- Sidewalks are present on the south side of the corridor.



Rear end crashes likely caused by:

- Minimal access management
- Variable speeds and sudden stops



Angle crashes likely caused by:

- Minimal access management
- Impatient drivers turning from side streets

