


DIAGNOSIS AND PROBLEM IDENTIFICATION


VTrans Needs Evaluation and Preliminary Alternatives





Recommended to conduct a separate Interchange Access Report for this interchange to improve weave safety conditions





Lack of Bicycle Facilities - Bicycle lanes are not present along the corridor.

- Sidewalks are not present north of Watson Street. except around the Christopher Lane intersection.

Future Development -Caesars Virginia is being constructed on Main Street.

-Residential development is anticipated along the

-There are no transit routes along Central Boulevard, within the study area limits.

